

02721 Untreated Base Course**02721** Standard Specification**Related Items:** N/A**Type of Construction:** Untreated Base Course**Submittals:****Quality Assurance:** Wear * AASHTO T-96**Assurance Frequency:** Submit a 200 lb sample of aggregate per source, use form T-268**Point of Acceptance:** Materials Source**Out of Spec Action:** Contractor must select another materials source.**Documentation/Report:****Type of Construction:****Submittals:****Quality Assurance:** Unit Weight * AASHTO T-19**Assurance Frequency:** Submit a 200 lb sample of aggregate per source, use form T-268.**Point of Acceptance:** Materials Source**Out of Spec Action:** Contractor must select another materials source.**Documentation/Report:****Type of Construction:****Submittals:****Quality Assurance:** Liquid Limit * AASHTO T-89 Plasticity Index * AASHTO T-90**Assurance Frequency:** Submit a 50 lb sample of aggregate per source, use form T-268.**Point of Acceptance:** Materials Source**Out of Spec Action:** Contractor must select another materials source.**Documentation/Report:**

Related Items: N/A**Type of Construction:****Submittals:****Quality Assurance:** Liquid Limit AASHTO T-89, Plasticity Index AASHTO T-90**Assurance Frequency:** A minimum of one determination per five test lots. (A minimum of one determination per source.)**Point of Acceptance:** Grade**Out of Spec Action:** Remove and replace with specification material.**Documentation/Report:****Type of Construction:****Submittals:****Quality Assurance:** Sieve Analysis AASHTO T-27 & T-11**Assurance Frequency:** A minimum of five determinations when the daily production exceeds 2,500 tons, a minimum of four determinations when it is between 1,500 and 2,500 tons, and a minimum of three determinations when less than 1,500 tons. (A minimum of one determination per 500 tons.)**Point of Acceptance:** Grade**Out of Spec Action:** Correct or remove and replace with specification material, or appropriate price reduction.**Documentation/Report:****Type of Construction:****Submittals:****Quality Assurance:** Lab Density AASHTO T-180 Method D**Assurance Frequency:** A minimum of one test per 11,000 tons.**Point of Acceptance:** N/A**Out of Spec Action:** N/A**Documentation/Report:**

Related Items: N/A

Type of Construction:**Submittals:****Quality Assurance:** Field Density and Moisture Content by Nuclear Gage AASHTO T-310**Assurance Frequency:** A minimum of one determination per subplot of approximately**Point of Acceptance:** Grade**Out of Spec Action:** Contractor must continue to compact until density meets specification.**Documentation/Report:**

Type of Construction:**Submittals:****Quality Assurance:** Test Report**Assurance Frequency:** Submit form T-138 or computer printout weekly.**Point of Acceptance:** N/A**Out of Spec Action:** N/A**Documentation/Report:**